## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.






FIG. 1B




FIG. 2A





FIG: 2B



Repair information	Product name	Manufacturer name	Type number	Warranty period	State of failure:		

FIG. 4

96	Others	64MB, No parity	1GB, Built-in, IDE	
on databas	Provider of product	Ь	Ö	
Component information database	Type number of pruduct	1987–115	432–5G	
omponent	Product name	Personal computer	Personal computer	
Ŏ	Component Type number name of component	0011–64	Y015–1G	
	Component	Memory	Disk	

FIG. 5




FIG. 6





FIG. 7







FIG. 9



103					
7					
	ase	Manufacturer name	۵ ۵۰۰۰	o o	
	Repairer database	Type	YAP-6001 YAP-6002	6GS-331 6GS-333 :	
	Rep	Name of a product that can be repaired	Personal computer	Personal computer	
		Repairer name	×	Y	

FIG. 11




FIG. 12




FIG. 13